

COMB (Orbital Products)

		1997-1998																														
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Dec-97									*1	*1	*1	*1				*1	*1	*1		*1												
Jan-98													*1			*1		*1														
Feb-98																																
Mar-98												*2																				
Apr-98																																
May-98																																
Jun-98																																
Jul-98																																
Aug-98																																
Sep-98																																
Oct-98																																
Nov-98																																
Dec-98																																

		1999																														
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-99												*3	*3	*3	*3																	
Feb-99																																
Mar-99																																
Apr-99																																
May-99																																
Jun-99																																
Jul-99																																
Aug-99																																
Sep-99																																
Oct-99																																
Nov-99																																
Dec-99																																

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2000																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-00																															
Feb-00																															
Mar-00																															
Apr-00																															
May-00																															
Jun-00																															
Jul-00																															
Aug-00																															
Sep-00																		*5	*5	*5			*2								
Oct-00																															
Nov-00																			*4												
Dec-00																															

	2001																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-01																															
Feb-01																															
Mar-01																															
Apr-01																															
May-01																															
Jun-01																															
Jul-01																															
Aug-01							*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6	*6								
Sep-01																															
Oct-01																															
Nov-01																			*4												
Dec-01																															

- *1 All scan calibration mode (E/G)
 - *2 Low Power Mode
 - *3 Sun Acquisition Mode
 - *4 Leonid Meteor Storm
 - *5 Instrument Anomaly
 - *6 Orbit boost (see Note)
 - *7 Solar Array Anomaly
 - *8 Recorder over flow
 - *9 KaPR Sampling Mode
 - *10 TDRS Anomaly
 - *11 Packet length error
 - *12 PR B side change (FCIF/SCDP)
 - *13 Ground facility Anomaly
 - *14 Unexpected attitude behavior (The products except 1B21 are E/G)
 - *15 Completion of PR Normal Mission Operation (NO DATA)
 - *16 Instrument powered off
- : All products available

: Some products unavailable

: All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2002																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-02																															
Feb-02																															
Mar-02																															
Apr-02																															
May-02																															
Jun-02																															
Jul-02																															
Aug-02																															
Sep-02																															
Oct-02																															
Nov-02																															
Dec-02																															

	2003																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-03																															
Feb-03																															
Mar-03																															
Apr-03																															
May-03																															
Jun-03																															
Jul-03																															
Aug-03																															
Sep-03																															
Oct-03																															
Nov-03																															
Dec-03																															

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2004																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-04																															
Feb-04																															
Mar-04																															
Apr-04																															
May-04																															
Jun-04				*8																											
Jul-04																															
Aug-04																															
Sep-04																															
Oct-04																															
Nov-04																															
Dec-04																															

	2005																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-05																															
Feb-05																															
Mar-05																															
Apr-05																															
May-05																															
Jun-05																															
Jul-05																															
Aug-05																															
Sep-05																															
Oct-05																															
Nov-05																															
Dec-05																															

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2006																															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
Jan-06																																
Feb-06																																
Mar-06																																
Apr-06																																
May-06																																
Jun-06																																
Jul-06																																
Aug-06																																
Sep-06																																
Oct-06																																
Nov-06																																
Dec-06																																

	2007																															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
Jan-07																																
Feb-07																																
Mar-07															*9	*9																
Apr-07																																
May-07																																
Jun-07																																
Jul-07										*10																						
Aug-07																																
Sep-07																																
Oct-07																																
Nov-07																																
Dec-07																																

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2008																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-08																															
Feb-08																															
Mar-08																															
Apr-08																															
May-08																															
Jun-08																															
Jul-08																															
Aug-08																															
Sep-08																															
Oct-08																															
Nov-08																															
Dec-08																															

	2009																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-09																															
Feb-09																															
Mar-09																															
Apr-09																															
May-09												*11																			
Jun-09	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12	*12											
Jul-09																															
Aug-09																															
Sep-09																															
Oct-09																															
Nov-09																															
Dec-09																															

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2010																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-10																															
Feb-10																															
Mar-10																															
Apr-10																															
May-10																															
Jun-10																															
Jul-10																															
Aug-10																			*8	*8											
Sep-10																															
Oct-10																															
Nov-10																															
Dec-10																															

	2011																														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-11																															
Feb-11																															
Mar-11																															
Apr-11																															
May-11																															
Jun-11																															
Jul-11																															
Aug-11																															
Sep-11																															
Oct-11																															
Nov-11																															
Dec-11																															

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

	2012																															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
Jan-12																																
Feb-12																																
Mar-12																																
Apr-12																																
May-12																																
Jun-12																																
Jul-12																																
Aug-12																																
Sep-12																																
Oct-12																																
Nov-12																																
Dec-12																																

	2013																															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
Jan-13																																
Feb-13																																
Mar-13																																
Apr-13																																
May-13																																
Jun-13																																
Jul-13																																
Aug-13																																
Sep-13																																
Oct-13																																
Nov-13												*13	*14	*14	*14					*13												
Dec-13																																

- *1 All scan calibration mode (E/G)
- *2 Low Power Mode
- *3 Sun Acquisition Mode
- *4 Leonid Meteor Storm
- *5 Instrument Anomaly
- *6 Orbit boost (see Note)
- *7 Solar Array Anomaly

- *8 Recorder over flow
- *9 KaPR Sampling Mode
- *10 TDRS Anomaly
- *11 Packet length error
- *12 PR B side change (FCIF/SCDP)
- *13 Ground facility Anomaly
- *14 Unexpected attitude behavior (The products except 1B21 are E/G)

- *15 Completion of PR Normal Mission Operation (NO DATA)
- *16 Instrument powered off

- : All products available
- : Some products unavailable
- : All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.

COMB (Orbital Products)

		2014																														
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-14																																
Feb-14																						*10										
Mar-14																																
Apr-14																																
May-14																																
Jun-14																																
Jul-14																																
Aug-14											*1	*1	*1	*1	*1	*1	*1	*1														
Sep-14																																
Oct-14									*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	
Nov-14		*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15
Dec-14		*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15

		2015																														
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Jan-15		*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15
Feb-15		*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15	*15																			
Mar-15																																
Apr-15		*16																														

- *1 All scan calibration mode (E/G)
 - *2 Low Power Mode
 - *3 Sun Acquisition Mode
 - *4 Leonid Meteor Storm
 - *5 Instrument Anomaly
 - *6 Orbit boost (see Note)
 - *7 Solar Array Anomaly
 - *8 Recorder over flow
 - *9 KaPR Sampling Mode
 - *10 TDRS Anomaly
 - *11 Packet length error
 - *12 PR B side change (FCIF/SCDP)
 - *13 Ground facility Anomaly
 - *14 Unexpected attitude behavior (The products except 1B21 are E/G)
 - *15 Completion of PR Normal Mission Operation (NO DATA)
 - *16 Instrument powered off
- : All products available

: Some products unavailable

: All products unavailable

Note: It boosted TRMM's orbit altitude to 402.5 km where the spacecraft kept from August 2001 to October 2014. The original flight altitude was 350 km in the other period.